



सासवड नगरपरिषद कार्यालय

सासवड, ता. पुरंदर, जि. पुणे

Ema ID- saswadmc@gmail.com

फोन नं :- ०२११५-२२२३४९, २२२४३७

जावक क्र. १००८

दिनांक. २९ / ८ / २०२०

प्रति,

प्राचार्य, शिवाजी इंग्लिश
मिडियम स्कूल,
सासवड, ता. पुरंदर जि. पुणे.

विषय :- स्ट्रक्चरल ऑडीट रिपोर्ट.

संदर्भ :- प्राचार्य, शिवाजी इंग्लिश मिडियम स्कूल यांचा दि. ०९/०८/२०२०
रोजीचा अर्ज.

सदरील अर्जाचे अवलोकन केले असता दि. १२/०८/२०२० रोजी बांधकाम विभागातील अभियंत्याने प्रत्यक्ष इमारतीची पहाणी केली. इमारतीचे सर्व स्ट्रक्चरल इलेमेन्डस व आर.सी.सी इलेमेन्डस सद्यस्थितीत समाधानकारक आहे. (स्टेअर केस, बिम कॉलम, पॅसेज व इतर स्ट्रक्चरल कॉम्पोनन्ड) सुस्थितीत आहेत. इमारतीची पहाणी खालीलप्रमाणे करण्यात आली.

- १) इमारत जी + ३ स्वरूपाची असून त्याचे स्ट्रक्चरल इलेमेन्डस सुस्थितीत आहेत.
- २) फाऊंडेशन कॉलम व फुर्डींगची साईज व काँक्रीटची धारक क्षमता सादर केलेल्या नकाशाप्रमाणे आहेत.
- ३) कॉलमचे कोणत्याही प्रकारचे तडे गेलेले नाही व सुस्थितीत आहेत.
- ४) इमारतीचे बिम सुस्थितीत असून कोणत्याही प्रकारचे विक्षेपण दिसून येत नाही.

शेरा :- एकुण इमारतीची पहाणी केली असता इमारत सद्यस्थितीला सुस्थितीत आहे.



(Signature)

बांधकाम विभाग प्रमुख
सासवड नगरपरिषद, सासवड



Saswad Municipal Council Office

Saswad, Tal. Purandar Dist. Pune

Email – saswadmc@gmail.com

Ph No. (Off.) 02115 – 222349, 222437

Out No. : 1008

Date : 21/08/2020

To,

The Principal

Shivaji English Medium School

Saswad, Tal. - Purandar, Dist - Pune.

Subject :- Structural Audit Report.

Reference :- Application by Principal, Shivaji English Medium School dated 09/08/2020

In accordance with application an engineer from Construction department had actually visited the site (building) and inspected the building on 12/08/2020. We have found that all the structure, elements and R.C.C. elements (Staircase, Beam Columns, Passage and other Structural Components) are in good condition as of now. Following facts were noted while inspecting the building –

- 1) Building is in (G+3) form with all structural elements in good condition.
- 2) Foundation column, footing size and concrete capacity are in accordance with map (provided)
- 3) No crack is found in columns and they are in good condition.
- 4) Beams of the building are in good condition and no deflection in beams is found.

Remark:- After inspecting the whole building, it's found that this building is in good condition as of now.



Signature

Head of the construction department,
Saswad Nagar Parishad, Saswad

I certify that I am competent to translate from Marathi to English and that the above Certificate is a complete and accurate translation to the best of my knowledge and belief.

Signature of Translator:-

Name of Translator :- Adv. Shashank Madhukar Jagtap

Address:- Opp. Shri . Kalawati Mata mandir, Jagtap Ali,
Old Post office, Saswad, Tal:- Purandar, Dist:- Pune

Mobile No. :- 9405436707

Date :- 21/08/2020

Manika Singh
MANAGER
Shivaji English Medium School
Saswad, Tal. Purandar, Dist. Pune

Shashank M. Jagtap
Adv. Shashank M. Jagtap
B.A., LL.B.
R/o- Opp. Kalawati Mata Mandir
Jagtap Ali, Saswad, Tal- Purandar,
Dist- Pune- 412301
MAN/2003/2003, Mob.- 9405436707

Ms. Lathak
PRINCIPAL
Shivaji English Medium School
Saswad, Tal. Purandar, Dist. Pune